

EL MONTE UNION HIGH SCHOOL DISTRICT

Purchasing Department

3537 JOHNSON AVENUE, EL MONTE, CA 91731 Phone: (626) 444-9005

Email: purchasing@emuhsd.org

May 17, 2024

TO : All Bidders

FROM : El Monte Union High School District

BID # : Bid No. 2023-24(B9)

PROJECT : South El Monte High School Building L Kitchen HVAC Project

SUBJECT : Addendum No. 1

The following changes, omissions, and/or additions to the Project Manual and/or Drawings shall apply to proposals made for and to the execution of the various parts of the work affected thereby, and all other conditions shall remain the same.

Careful note of the Addendum shall be taken by all parties of interest so that the proper allowances may be made in strict accordance with the Addendum, and that all trades shall be fully advised in the performance of the work which will be required of them.

Bidder shall acknowledge receipt of this Addendum in the space provided on the Bid Form. Failure to do so may subject Bidder to disqualification.

In case of conflict between Drawings, Project Manual, and this Addendum, this Addendum shall govern.

REVISIONS TO BID DOCUMENTS

- Clarification of bid submission. All bids must be submitted in physical form at the Purchasing Department located at 1003 Durfee Ave., South El Monte, CA 91733. Map attached.
- 2. Site photos and roof access hatch locations attached.

ATTACHMENTS

- 1. Purchasing Department Map
- 2. Site photos and roof access hatch locations


END OF ADDENDUM NO. 1




Purchasing Department
1003 Durfee Avenue
South El Monte, CA 91733
(626) 444-9005 Ext. 9850 or 9851

Bid Drop-Off Enterance EMUHSD Purchasing Office











Description Roof access hatch and roof condition at existing unit.

Taken Date 05/16/2024 at 02:00 pm

Upload Date 05/16/2024 at 02:14 pm

Uploaded By Mike Harris

File Name 96B3A07E-82E6-4344-9...



BP 20: Bldg. L Kitchen HVAC

Description
Roof condition depicting
(2) existing units.

Taken Date 05/16/2024 at 02:00 pm

Upload Date 05/16/2024 at 02:14 pm

Uploaded By Mike Harris

File Name 02463F3C-C959-4E3E-A...







Description
Roof condition depicting
(1) existing unit.

Taken Date 05/16/2024 at 01:59 pm

Upload Date 05/16/2024 at 02:15 pm

Uploaded By Mike Harris

File Name BA83B961-3840-4516-A...



BP 20: Bldg. L Kitchen HVAC

Description
Roof condition depicting
(1) existing unit.

Taken Date 05/16/2024 at 01:59 pm

Upload Date 05/16/2024 at 02:15 pm

Uploaded By Mike Harris

File Name 00B8EE91-F9DC-4E17-8...







Description
Overall roof condition photo.

Taken Date 05/16/2024 at 01:59 pm

Upload Date 05/16/2024 at 02:15 pm

Uploaded By Mike Harris

File Name OBBCFA7A-3434-43CF-A...



BP 20: Bldg. L Kitchen HVAC


Description
Alt angle roof condition photo.

Taken Date 05/16/2024 at 01:59 pm

Upload Date 05/16/2024 at 01:59 pm

Uploaded By Mike Harris

File Name 130B4AE3-46B6-4BB3-8...








Description

Taken Date 05/16/2024 at 01:56 pm

Upload Date 05/16/2024 at 01:58 pm

Uploaded By Mike Harris

File Name EDEC6CA1-B6D4-4383-...



BP 20: Bldg. L Kitchen HVAC

Description
Ceiling condition above oven vent hood/grease trap.

Taken Date 04/24/2024 at 02:41 pm

Upload Date 05/17/2024 at 08:18 am

Uploaded By Dallas Moon

File Name A8F87CC8-5F24-4FD8-8...







Description
Ceiling condition below existing unit in kitchen.

Taken Date 04/24/2024 at 02:38 pm

Upload Date 05/17/2024 at 08:18 am

Uploaded By Dallas Moon

File Name DC6F2647-81A9-43DC-8...



BP 20: Bldg. L Kitchen HVAC


Description Ceiling condition below existing unit in kitchen.

Taken Date 04/24/2024 at 02:38 pm

Upload Date 05/17/2024 at 08:18 am

Uploaded By Dallas Moon

File Name 942DCB6B-FEBF-4B85-B...








Description
Ceiling condition above
oven vent hood/grease
trap in kitchen.

Taken Date 04/24/2024 at 02:37 pm

Upload Date 05/17/2024 at 08:18 am

Uploaded By Dallas Moon

File Name 54D90AD3-0C70-4ABF-8...



BP 20: Bldg. L Kitchen HVAC


Description
Ceiling condition at
existing unit in kitchen.

Taken Date 04/24/2024 at 02:37 pm

Upload Date 05/17/2024 at 08:18 am

Uploaded By Dallas Moon

File Name 3D39A7AC-4CB9-401C-...







Description
Ceiling condition at
existing unit in kitchen.

Taken Date 04/24/2024 at 02:36 pm

Upload Date 05/17/2024 at 08:18 am

Uploaded By Dallas Moon

File Name 38B2A355-127E-4943-8...

